



*Cofe*

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re U.S. Patent No: 7,275,771 B2

Inventor(s): Crotti et al.

Serial No. 10/517,953

Examiner: Glessner

Issued: October 2, 2007

Group Art Unit: 3676

Title: **LOCK FOR A DOOR OF A MOTOR VEHICLE**

Attorney Docket No: 19339-099974

Mail Stop Certificate of Correction Branch  
Commissioner of Patents  
PO Box 1450  
Alexandria, VA 22313-1450

*Certificate  
OCT 16 2007  
of Correction*

### REQUEST FOR CERTIFICATE OF CORRECTION

Dear Sir:

Patentees request a Certificate of Correction for U.S. Patent No. 7,275,771 B2 issued October 2, 2007. Upon reviewing the issued patent, the patentee noted that the following errors were made, which should be corrected as follows:

In Column 3, line 16, please correct as follows:

[BEST MODE FOR CARRYING OUT THE INVENTION] DETAILED DESCRIPTION  
OF PREFERRED EMBODIMENT

In Column 6, lines 58-59, please correct as follows:

...in which the auxiliary [the] safety member 58....

*OCT 16 2007.*

Since this is a USPTO error, there should be no fee for this Certificate of Correction.

Respectfully submitted,

CLARK HILL PLC



Date 10/9/07

Robin W. Asher, Reg. No. 41,590  
500 Woodward Avenue, Suite 3500  
Detroit, MI 48226-3435  
(313) 965-8300  
Attorney for Patentees

# UNITED STATES PATENT AND TRADEMARK OFFICE

## CERTIFICATE OF CORRECTION

PATENT NO. : 7,275,771 B2

DATED : October 2, 2007

INVENTOR(S) : Crotti et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In Column 3, line 16:

[BEST MODE FOR CARRYING OUT THE INVENTION] DETAILED DESCRIPTION OF THE PREFERRED EMBODIMENT

In Column 6, lines 58-59:

...in which the auxiliary [the] safety member 58....

MAILING ADDRESS OF SENDER (Please do not use customer number)

Robin W. Asher, Reg. No. 41,590, Clark Hill PLC, 500 Woodward  
Avenue, Suite 3500, Detroit, MI 48226-3435

PATENT NO. 7,275,771

No. of additional copies



OCT 16 2007